



Site: 005 Homestead Structural Artifacts (PN99-0424-1-6)



Site: 005 Gravel Pit (PN99-0424-1-7)



Site: 005 Gravel Pit/Mound (PN99-0424-1-8)

Attachment B

Supporting Information for Site #005

435.36 04/14/99 Rev. 03

NEW SITE IDENTIFICATION

		n
1.	Person Initiating Report: Jacob Harris	Phone: 526-1877
	Contractor WAG Manager: Douglas Burns	Phone: 526-4324
2.	Site Title: 005, Excavation Pit/Mound and Debris East of Guard Gate 3	
3.	Describe the conditions that indicate a possible inactive or unreported was condition, amount or extent of condition and date observed. A location mesurvey points or global positioning system descriptors shall be included to names or location descriptors for the waste site.	nap and/or diagram identifying the site against controlled
	There is a large excavation pit/mound, debris and 2 small pits about 200 visit, the observed surface debris included glass, metal, wire, wood, and associated with the debris. One pit contains concrete and old pieces of w pit/mound appears to be from a separate excavation activity. The GPS of the reference number for this site is 005 and can be found on the summary	rusted cans. There are 2 small pits that apear to be rood and the other contains wood. The large gravel cordinates for this site are
Dar	t B – To Be Completed By Contractor WAG Manager	
4.	Recommendation:	
	X This site meets the requirements for an inactive waste site, requires FFA/CO Action Plan. Proposed Operable Unit assignment is recom WAG:	
	This site DOES NOT meet the requirements for an inactive waste sit included in the INEEL FFA/CO Action Plan.	e, DOES NOT require investigation and SHOULD NOT be
5.	Basis for the recommendation:	
	The conditions that exist at this site indicate the potential for an inactive or Disturbance of Suspected Inactive Waste Sites.	vaste site according to Section 2 of MCP-3448 Reporting
		, and the second se
	The basis for recommendation must include: (1) source description; (2) concern; and (4) descriptions of interfaces with other programs, as applic	
6.	Contractor WAG Manager Certification: I have examined the proposed size believe the information to be true, accurate, and complete. My recomme	
	ne: Signature:	Date:

	aboratory
	onmental L
	daho National Engineering & Environmental I
	al Engìneer
	ho Nation
	daho

PROJECT DOCUMENT REVIEW RECORD

DOCUMENT TITLE/DESCRIPTION:	CRIPTION:	Site 005 Track 1 Decision Documentation Package, OU 10-08: Excavation Pit/Mound and Debris East of	cavation Pit/Mound and Debris East of
		Guard Gate 3 (DOE/ID 10934)	
DATE: March 29, 2002		REVIEWER: IDEQ	
ITEM SECTION NUMBER	PAGE NUMBER	COMMENT	RESOLUTION
COMMENTS			
1	∞	The second paragraph states "The volume of pit/hole is consistent." Please clarify what the volume of the pit/hole is consistent with. The reader may assume it is consistent with the volume of the mound but it is not clear. Please clarify.	Comment incorporated. However, because a previous sentence in the paragraph already stated, "The pit and mound are very similar in size," we have deleted the unclear sentence: "The volume of pit/hole is consistent."
2	6	The second paragraph of Block I states "The gravel was likely used for present-day INEEL road construction activities." If material was removed then the volumes of the pit and mound should not be consistent as inferred on page 8. Please clarify.	Comment incorporated. We have deleted the sentence.
٣	Attachment B. New Site Identification Form	Last page - Part 3 states the site number 016 but the rest of the description is for site 005. This was probably a collating error when assembling the packets.	Comment incorporated. We have changed the "016" to "005."